



Anthony HARRIS
Andrew STROUD

Vicroads





- Tow coupling routine stop



VIDEO TO GO IN HERE



Bartlett ball broken tension spring





Head of draw bar broken away
Old age , metal fatigue and poor welding





Cracked fifth wheel

